# **Richmond Refinery LPS Alert – Safety**







**IMPACT ERM: 24256** 

### Location:

Richmond Refinery Richmond, CA, USA

#### Contact Information:

Michelle Johansen CTN 242-4343 MJohansen@chevron.com

## Reference:

Information



General Entry Confined Space Permit

Always remember to do your LPSA.

## **Incident Description:**

On October 20, 2011, a Chevron employee was set to provide a final cleanliness inspection on F-1251 during the RLOP turnaround. There was an entry attendant and permit located at the opening to this furnace. The employee reported to the attendant for entry and signed in. The attendant removed the red tape over the confined space opening and then turned around to check the PPE Matrix packet. The employee, thinking it was OK, proceeded to enter. The attendant immediately asked the employee to come back out of the furnace. It was identified that the confined space permit had expired and the PPE identified for entry was incorrect. Both employees are Short Service Employees.

An investigation is in progress.

## **Immediate Actions Taken:**

- 1) Employee notified their supervisor of the event immediately and the Supervisor called Chevron Fire Dept to assess the situation.
- 2) Safety stand down meetings were held to find out where process breakdown had occurred.
- 3) Issuing this LPS Alert to inform others that are performing similar work to check the entry permit prior to confined space entry (to include checking the expiration date on entry permits and entry PPE matrix requirements). Conduct an LPSA to understand the risk of entry and ensure mitigating actions are taken.



This document is intended for company workforce only. Nothing herein should be construed as a legal determination of causation or responsibility. The company makes no representations or warranties, express or implied, about the thoroughness, accuracy, or suitability of use by others of any of the information contained herein.